ABS Consulting
上海埃比埃斯技术检验有限公司

Report No.:	Project No.:	Date:	Office:
10-7079-SQ-06	2313112	February 21, 2010	Shanghai

REPORT OF ACTIVITY

General Scope of Activity:	Dates of All Related Activity:
Third party inspection	February 10, 2010
Client:	**Supplier:**
Company Name: GOFORTH CORPORTION SDN BHD Address: --- Contact(s): ---	Company Name: Rugao Haiyang Marine Equipments Foundry Address: Changjiang Town, Rugao Jiangsu Province, China Contract(s): Ms. Wang Li
Component Description(s):	**Results:**
Witness proof test on grapnel	**Results**: Meets requirements ☐ Subject to condition(s) noted ☒ Does not meet requirements ☐

THIS IS TO CERTIFY THAT the undersigned representatives of ABS Consulting Shanghai did, at the request of Rugao Haiyang Marine Equipments Foundry, attend Rugao Haiyang Marine Equipments Foundry on February 10, 2010 in order to witness proof test on grapnel and report as follows:

1.0 Scope of service activity:

.1 Reviewed drawing and heat treatment record,
.2 Visual inspection after proof testing,
.3 Issued the report of activity.

CL... ...I COPY
P/O NO. : SCY/SP/10-10-01
D/O NO. : 03579
DATE : 11-10-10

2.0 Details:

- ABS consulting representative reviewed the drawing and heat treatment record;
- ABS consulting representative reviewed the calibration certificate of the test equipments.
- Visual inspection on the surface after proof testing.

Proof test process and test results:

Item	Production S/N	SWL (Ton)	Proof Load (KN)	Duration time(MIN)	Results
1	1002021	110	1440/1430	5	Satisfied

ABS CONSULTING INC.

This certificate is granted subject to the condition that it is understood and agreed that nothing herein contained shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer or operator of any warranty, express or implied and ABS Group Inc. liability shall be limited to the acts or omissions of its employees, agents, and subcontractors. Under no circumstance whatsoever shall ABS Group Inc. be liable for any injury or damage to any person or property occurring by reason of negligent operation or any defect in materials, machinery, equipment or other items other than defects ascertainable by normally accepted testing standards, and only upon those items actually inspected by ABS Group Inc. and which are covered by this certificate or report.

Report No.:	Project No.:	Date:	Office:
10-7079-SQ-06	2313112	February 21, 2010	Shanghai

3.0 Identification of items verified:

See section 2

4.0 Conclusion:

- Visual inspection after proof test, the surface has not been found evidently cracks and permanent distortion. After finished above activity, ABS representative stamped ABS consulting logo 'wTs' on the grapnel.
- The proof test values are satisfied to the specified drawing.

5.0 Attachments:

No

Report prepared and submitted without prejudice.

QS Zhang
Technical Representatives
ABS Consulting Shanghai

CERTIFIED TRUE COPY
P/O NO. : 3L4/SPL 10-10-07
D/O NO. : 03578
DATE : 11-10-10

This certificate is granted subject to the condition that it is understood and agreed that nothing herein contained shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer or operator of any warranty, express or implied and ABS Group Inc. liability shall be limited to the acts or omissions of its employees, agents, and subcontractors. Under no circumstance whatsoever shall ABS Group Inc. be liable for any injury or damage to any person or property occurring by reason of negligent operation or any defect in materials, machinery, equipment or other items other than defects ascertainable by normally accepted testing standards, and only upon those items actually inspected by ABS Group Inc. and which are covered by this certificate or report.