



ABS Consulting

上海埃比埃斯技术检验有限公司

| | | | |
|------------------------------|-------------------------|----------------------------|---------------------|
| Report No.: 10-7079-SQ-04 | Project No.: 2313112 | Date: February 21, 2010 | Office: Shanghai |
|------------------------------|-------------------------|----------------------------|---------------------|

REPORT OF ACTIVITY

| | |
|---|---|
| General Scope of Activity: Third party inspection | Dates of All Related Activity: February 10, 2010 |
| Client: Company Name: GOFORTH CORPORTION SDN BHD Address: --- Contact(s): --- | Supplier: Company Name: Rugao Haiyang Marine Equipments Foundry Address: Changjiang Town, Rugao Jiangsu Province, China Contract(s): Ms. Wang Li |
| Component Description(s): Witness proof test on hook | Results: Results: Meets requirements <input type="checkbox"/> Subject to condition(s) noted <input checked="" type="checkbox"/> Does not meet requirements <input type="checkbox"/> |

THIS IS TO CERTIFY THAT the undersigned representatives of ABS Consulting Shanghai did, at the request of Rugao Haiyang Marine Equipments Foundry, attend Rugao Haiyang Marine Equipments Foundry on February 10, 2010 in order to witness proof test on hook and report as follows:

1.0 Scope of service activity:

- .1 Reviewed drawing and heat treatment record.
- .2 Visual inspection after proof testing,
- .3 Issued the report of activity.

CERTIFIED TRUE COPY

P/O NO. : 24/02/10-10-01

D/O NO. : 02578

DATE : 11-10-10

2.0 Details:

- ABS consulting representative reviewed the drawing and heat treatment record;
- ABS consulting representative reviewed the calibration certificate of the test equipments.
- Visual inspection on the surface after proof testing.

Proof test process and test results:

| Item | Production S/N | SWL (Ton) | Proof Load (Ton) | Duration time(MIN) | Results |
|------|----------------|-----------|------------------|--------------------|-----------|
| 1 | 1002019 | 110 | 140 | 5 | Satisfied |

This certificate is granted subject to the condition that it is understood and agreed that nothing herein contained shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer or operator of any warranty, express or implied and ABS Group Inc. liability shall be limited to the acts or omissions of its employees, agents, and subcontractors. Under no circumstance whatsoever shall ABS Group Inc. be liable for any injury or damage to any person or property occurring by reason of negligent operation or any defect in materials, machinery, equipment or other items other than defects ascertainable by normally accepted testing standards, and only upon those items actually inspected by ABS Group Inc. and which are covered by this certificate or report.





ABS Consulting

上海埃比埃斯技术检验有限公司

Page 2 of 2

| | | | |
|------------------------------|-------------------------|----------------------------|---------------------|
| Report No.: 10-7079-SQ-04 | Project No.: 2313112 | Date: February 21, 2010 | Office: Shanghai |
|------------------------------|-------------------------|----------------------------|---------------------|

3.0 Identification of items verified:

See section 2

4.0 Conclusion:

- Visual inspection after proof test, the surface has not been found evidently cracks and permanent distortion. After finished above activity, ABS representative stamped ABS consulting logo 'wTs' on the hook.
- The proof test values are satisfied to the specified drawing.


5.0 Attachments:

No

Report prepared and submitted without prejudice.



QS Zhang
Technical Representatives
ABS Consulting Shanghai



This certificate is granted subject to the condition that it is understood and agreed that nothing herein contained shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer or operator of any warranty, express or implied and ABS Group Inc. liability shall be limited to the acts or omissions of its employees, agents, and subcontractors. Under no circumstance whatsoever shall ABS Group Inc. be liable for any injury or damage to any person or property occurring by reason of negligent operation or any defect in materials, machinery, equipment or other items other than defects ascertainable by normally accepted testing standards, and only upon those items actually inspected by ABS Group Inc. and which are covered by this certificate or report.